



March 21, 2018

Addendum #1 Crackfilling Revised Quantity

Instructions

Sign the addendum page below. Return this sheet and the attached pages with your bid.

Summary

The Schedule of Prices has been revised. The BLR 12200a has been revised to show 66,000LB of Crack Filler and 198,000 LF of Crack Routing.

Company Name: _____

Company Representative(Print Name): _____

Signature of Company Representative: _____

Date: _____

RETURN WITH BID

Bidder's Proposal for making Entire Improvements

Item No.	Items	Unit	Quantity	Unit Price	Total